

AGENDA ITEM
September 17, 2019

Subject: Repair 500 Block of South Lynn St.

Department: Public Works

In the 500 block of South Lynn Street, the storm tube bottoms have rusted away allowing the tubes to start to collapse under the street. I would like to replace them with 6 x 6 concrete boxes. The road has been closed for about two months.

The following businesses were contacted and below are the bids received:

Vendor	Total Bid
Scurlock Industries	16,800.00
Barbour Concrete	No response to request
Stewart Concrete	No response to request