

**AGENDA ITEM**  
February 18, 2020

Subject: Truck Repair

Department: Public works

Bids were solicited to repair Public Work's 2018 GMC 3500HD Sierra crew truck. This vehicle was involved in an accident on October 16, 2019, at Hickory & Washington when a driver didn't stop at the intersection and struck the truck's left side. Coale Body Shop was chosen because OEM replacements parts were used and not After-Market. The head light assembly was not included in the quotes which caused the total cost to exceed \$5000.00

Vendor	Total Bid
Keith's Body Shop	4,193.00
Coale Body Shop	4,697.33

**Managers Note:** On December 4, 2019, Insurance (claim #608105) reimbursed the City \$4811.46. The additional parts and installation caused the check issued to Coale Body Shop to be over \$5000.00. This amount by code Section 26-9 requires Council approval. Check in the amount of \$5,143.65 was issued on February 7, 2020

Section 26-9 (2) (b): *Methods.* Contracts for services, the cost of which exceeds \$5,000.00, other than those exempted in subsection 2.d of this section, whenever practical, shall be based on at least two responses to RFPs or RFQs or competitive bids

Section 26-9 (2) (e): Basis of award. The basis for an award of contract for services, depending on the complexity of the service, becomes dependent (increasingly with complexity) on the ability, capacity, reliability and availability of the contractor and the nature of the city's demand for said services, and does not necessarily depend on the charge, price or hourly rate, since all vendors will not provide identical quality and expertise. Such contracts may be negotiated by the city purchasing agent or his deputies; however, said contracts require council approval except in an emergency.



**Preliminary Estimate**

**Customer: CITY of NEVADA PUBLIC WORKS DEPT.**

**Job Number:**

2018 GMC Sierra 3500 HD Crew Cab & Chassis 171.5" WB 59.06" 4WD 4D P/U 8-6.6L Turbocharged Diesel - TBD - WHITE

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		<b>FRONT BUMPER</b>					
2		O/H front bumper				3.7	
3	**	Repl A/M CAPA Bumper chrome w/o park assist	23178907	1	850.00	Incl.	
4	**	Repl A/M CAPA LT Outer bracket	23178908	1	188.00	Incl.	
5	**	Repl A/M KEYSIQ LT Guide bracket	23451021	1	16.00	Incl.	
6	**	Repl A/M KEYSIQ LT Outer brace	22774470	1	31.00	Incl.	
7		Repl LT Outer filler	23481684	1	107.78	0.3	0.5
8		Add for Clear Coat					0.1
9	**	Repl A/M KEYSIQ Step pad	23178912	1	65.00	Incl.	
10	**	Repl A/M CAPA Air deflector	23320648	1	241.00	Incl.	
11		<b>FRONT LAMPS</b>					
12	**	Repl A/M KEYSIQ LT Headlamp assy	84180592	1	1,265.00	0.3	
13		<b>FENDER</b>					
14	**	Repl A/M CAPA LT Fender	23303550	1	530.00	2.9	2.0
15		Overlap Minor Panel					-0.2
16		Add for Clear Coat					0.7
17		Add for dual battery				0.3	
18		Add for Edging					0.5
19		Add for Clear Coat					0.1
20		Add for Inside					1.2
21		Add for Clear Coat					0.2
22		Repl LT Fender liner	22763673	1	112.52	Incl.	
23	#	Repl Cover car		1	5.00		
24	#	Subl Hazardous waste removal		1	3.50 X		
<b>SUBTOTALS</b>					<b>3,414.80</b>	<b>7.5</b>	<b>5.1</b>

**ESTIMATE TOTALS**

Category	Basis	Rate	Cost \$
Parts			3,411.30
Body Labor	7.5 hrs @	\$ 48.00 /hr	360.00
Paint Labor	5.1 hrs @	\$ 48.00 /hr	244.80
Paint Supplies	5.1 hrs @	\$ 34.00 /hr	173.40
Miscellaneous			3.50
Subtotal			4,193.00
<b>Grand Total</b>			<b>4,193.00</b>
Deductible			0.00
<b>CUSTOMER PAY</b>			<b>0.00</b>
<b>INSURANCE PAY</b>			<b>4,193.00</b>

**MyPriceLink Estimate ID / Quote ID:**

618538963514171392 / 57411400



Coale Body Shop  
 Clay Coale  
 14255 E. Stockade Road  
 Nevada, MO 64772  
 Business Phone: (417) 667-5959  
 Fax: (417) 667-5959

# Estimate

Est # 128  
 ID # 7450475

Vehicle Info: 2018 GMC -3500HD Sierra / 1GD42VCY7JF251778 / Body Type: 4 Door Crew Cab 168 / Production Date: APR-2018

Owner: City of Nevada / 501 S Jefferson / Nevada, MO 64772

Insurance Company: Inspection Date: 10/29/2019 /

Qper	Description	Part Number	Price	Labor
<b>FRONT BUMPER</b>				
1	Replace	FRT BUMPER IMPACT BAR	23178907	✓ \$999.98 Included
2	Overhaul	FRT BUMPER ASSY		3.2 hrs. Body
3	Replace	FRT LWR BUMPER AIR DEFLECTOR	23320648	✓ \$283.25 Included
4	Replace	FRT BUMPER SKID PLATE	23178779	✓ \$398.68 Included
5	Replace	L FRT BUMPER FILLER PANEL	23481684	✓ \$107.78 Included
				0.5 hrs. Paint panel
				0.2 hrs. Refinish
6	Replace	L FRT BUMPER IMPACT BRACKET	23178908	✓ \$248.63 0.4 hrs. Body
7	Replace	L FRT INR BUMPER BRACKET	22774466	✓ \$65.00 0.2 hrs. Body
8	Replace	L FRT BUMPER BRACE	22774470	✓ \$40.00
9	Replace	L FRT BUMPER GUIDE	23451021	✓ \$18.55
<b>FRONT FENDER</b>				
10	Replace	L FENDER PANEL	23303550	✓ \$602.13 5.2 hrs. Body
				2.4 hrs. Paint panel
				1 hrs. Clearcoat
				1.0 hrs. Refinish
11	Replace	L FENDER LINER	22763673	✓ \$112.52 Included
12	Replace	L FENDER WHEEL OPENING MLDG	22775550	✓ \$122.12 Included
13	Replace	L FENDER NAMEPLATE	22813983	✓ \$32.88 0.2 hrs. Body
<b>WHEEL</b>				
14	Replace	FRT WHEEL HUB CAP	9597799	✓ \$68.83
15	Repair	WHEEL		1 hrs. Body
16	R&I	WHEEL		0.3 hrs. Body
				1 hrs. Paint panel
				0.4 hrs. Clearcoat
				0.4 hrs. Refinish
<b>FRONT DOOR</b>				
17	Repair	L FRT DOOR SHELL		0.5 hrs. Body
				2.6 hrs. Paint panel
				1 hrs. Clearcoat
				1.0 hrs. Refinish
18	Replace	L FRT DOOR ADHESIVE NAMEPLATE	15129646	✓ \$61.88 0.2 hrs. Body
<b>OTHER</b>				
19	Other	Sublet HAZARDOUS WASTE REMOVAL		✓ \$3.00

20 Other MOUNT & BALANCE

\$15.00

### Totals

Type	Labor Time	Cost	Total	Taxable
Body Labor	11.2	\$50.00	\$560.00	
Clearcoat Supplies	2.5	\$36.00	\$90.00	✓
Paint Labor	9.0	\$50.00	\$450.00	✓
Paint Supplies	6.5	\$36.00	\$234.00	✓
OEM Parts			\$3,162.23	✓
Other Parts			\$18.00	✓


Invoice  
 495  
 179.20  
 325  
 195  
 4645.45  
 3

Clearcoat Supplies capped at 2.5 hours  
 Clearcoat Labor capped at 2.5 hours

Taxable Amount		\$3,504.23
Tax	5.225%	\$183.10
Nontaxable Amount		\$1,010.00
Grand Total		\$4,697.33

4514.23 5805.65  
 Difference 1,291.42

This estimate is what we could see without teardown.



**Coale Body Shop**  
 Clay Coale  
 14255 E. Stockade Road  
 Nevada, MO 64772  
 Business Phone: (417) 667-5959  
 Fax: (417) 667-5959

**Final Bill**  
 Est # 128  
 ID # 7450475

**Vehicle Info:** 2018 GMC -3500HD Sierra / 1GD42VCY7JF251778 / Body Type: 4 Door Crew Cab 168 / Production Date: APR-2018  
**Owner:** City of Nevada / 501 S Jefferson / Nevada, MO 64772  
**Insurance Company:** Inspection Date: 10/29/2019 /

*Repair 2018 GMC Truck*

*\$5143.65*

Acct. # 200-5-4600-231  
 Dept. Head [Signature]  
 City Mgr/Pur. Agent \_\_\_\_\_

FEB 06 2020

Oper	Description	Part Number	Price	Labor
<b>FRONT BUMPER</b>				
1	Replace	FRT BUMPER IMPACT BAR	23178907	\$999.98 Included
2	Overhaul	FRT BUMPER ASSY		3.2 hrs. Body
3	Replace	FRT LWR BUMPER AIR DEFLECTOR	23320648	\$283.25 Included
4	Replace	FRT BUMPER SKID PLATE	23178779	\$398.68 Included
5	Replace	L FRT BUMPER FILLER PANEL	23481684	\$107.78 Included
				0.5 hrs. Paint panel
				0.2 hrs. Clearcoat
				0.2 hrs. Refinish
6	Replace	L FRT BUMPER IMPACT BRACKET	23178908	\$248.63 0.4 hrs. Body
7	Replace	L FRT INR BUMPER BRACKET	22774466	\$65.00 0.2 hrs. Body
8	Replace	L FRT BUMPER BRACE	22774470	\$40.00
9	Replace	L FRT BUMPER GUIDE	23451021	\$18.55
<b>* FRONT LAMPS</b>				
10	Replace	L FRT COMBINATION LAMP ASSEMBLY	84180592	\$1,483.22
<b>FRONT FENDER</b>				
11	Replace	L FENDER PANEL	23303550	\$602.13 5.2 hrs. Body
				2.4 hrs. Paint panel
				1 hrs. Clearcoat
				1.0 hrs. Refinish
12	Replace	L FENDER LINER	22763673	\$112.52 Included
13	Replace	L FENDER WHEEL OPENING MLDG	22775550	\$122.12 Included
14	Replace	L FENDER NAMEPLATE	22813983	\$32.88 0.2 hrs. Body
<b>WHEEL</b>				
15	Replace	FRT WHEEL HUB CAP	9597799	\$68.83
<b>FRONT DOOR</b>				
16	Repair	L FRT DOOR SHELL		0.5 hrs. Body
				2.6 hrs. Paint panel
				1 hrs. Clearcoat
				1.0 hrs. Refinish
17	Replace	L FRT DOOR ADHESIVE NAMEPLATE	15129646	\$61.88 0.2 hrs. Body
<b>OTHER</b>				
18	Other	Sublet HAZARDOUS WASTE REMOVAL		\$3.00

*Claim # 608105 Ins Paid us \$ 4911.46 12/4/19*

*-cell-*

# Totals

Type	Labor Time	Cost	Total	Taxable
Body Labor	9.9	\$50.00	\$495.00	
Clearcoat Supplies	2.2	\$36.00	\$79.20	✓
Paint Labor	7.7	\$50.00	\$385.00	
Paint Supplies	5.5	\$36.00	\$198.00	✓
OEM Parts			\$4,645.45	✓
Other Parts			\$3.00	✓
Taxable Amount			\$4,925.65	
Tax	0%		\$0.00	
Nontaxable Amount			\$880.00	
Grand Total			\$5,805.65	

## Payment Details

Name	Date	Description	Amount
Trexis Insurance	2/6/2020	Supplement Payment-Coming directly to our shop	\$662.00

Amount Payable: \$5,805.65

Payment Made: \$662.00

Amount Due: \$5,143.65

This estimate is what we could see without teardown. The only additional part was the left headlight.